

2004 Hawker 800XP SERIAL NUMBER 258645 | REG M-HSXP



Enrolled on MSP Gold | RVSM Capable | Enrolled on CAMP | Airshow 400

AIRFRAME:

Airframe Total Time: 4943 Total Landings: 2588

ENGINES:

Honeywell Model TFE731-5BR-1H on MSP Gold

Left Engine - S/N P107851 4916 Hours Total Time, 2576 Total Cycles

Right Engine - S/N P107847 4943 Hours Total Time, 2588 Total Cycles

APU:

Honeywell Model GTCP 36-150W **on MSP** S/N - P-747 4667 Hours Total Time

AVIONICS:

NAV: 2 COLLINS VIR 432A FMS: 2 COLLINS FMS 6000

FDS: COL FGC 3000 ADF: COL ADF 462 ALT: COLLINS ALT 4000

ADC: 2 COLLINS ADC 3000 CVR: UNIVERSAL CVR 120

DME: 2 COL DME 442 GPS: 2 COL 4000A

HFCOMM: COL HF 9000/SELCAL

AFIS: HONEYWELL COMM: 2 COL VHF 422C

AIRBORNE Phone: MAGNASTAR C2000

TCAS System Name: HNWYL TCAS 4000 Mode S TRANSPONDER: 2 COLLINS TDR 94D/MODE S

EGPWS: HONEYWELL MK V RADAR: COL TWR 850 CLR

INTERIOR:

Eight (8) passenger w/Beige lather seats, Fire-blocked, Aft Belted Lav. New carpet in 2015. Seats refurbished in 2015. An Airshow 400 system provides passengers with aircraft position and information data.

EXTERIOR:


Overall Matterhorn White with Red and Black accent stripes. New paint completed by Bizjet in November 2012.














Specifications and/or descriptions are provided as introductory information only, and do not constitute representations or warranties of Freestream Aircraft Limited. Accordingly, you should rely on your own inspection of the aircraft.

Subject to prior sale.