

# 1998 Challenger 604 SN 5368

---



T: +1 248.820.8936  
FREESTREAM.COM

Kevin Crowe  
kevin@freestream.com

# 1998 Challenger 604 SN 5368

## Airframe

Total Time: 11,528 hrs

Total Landings: 8,287

## ENGINES

### Engines

Model: GE CF34-3B

Engine 1: 11,528 hours/ 8,287 CY

Engine 2: 11,080 hours/ 7,888 CY

## APU

Model Honeywell GTCP 36-150

Hours: 9,670

## COMPREHENSIVE ONBOARD EQUIPMENT & ENHANCEMENTS

- Honeywell AIS-2000 DIRECTV;
- Grimes Upper and Lower Strobe Beacon Light;
- Airshow Genesys Cabin Information System;
- Tow Bar in Fwd Avionics Bay;
- 3 Additional Cabin Windows Installed;
- Service Door Micro Switches;
- Fwd L/H Wardrobe with Jump Seat;
- 2nd Cockpit Refuel / Defuel Panel;
- Pilot/Copilot Map Holder;
- Aft Bay Storage Box with Spare Wheel Attach;
- Two (2) 10-Man Life Rafts;
- Multiple 110 VAC Outlets Throughout Aircraft;
- Rosen Cockpit Sunvisors;
- Pulsating Wing Landing/Taxi Light System;
- Lavatory Mat Switch and Timer;
- Penny and Giles Cabin Display;
- IEC Cabin Management System;
- Two (2) LCD Cabin Monitors (15");
- CD Player;
- DVD Player;
- Video Cassette Player;
- Eight (8) Cabin Speakers and Two (2) Sub Woofers;
- Printer / Fax Machine.



## AVIONICS

- Six EFIS Display Tubes with EICAS (EFD-4077);
- Dual Collins FCC-4006 Digital Flight Control Systems;
- Dual Collins ADC-850E Digital Air Data Systems;
- Dual Collins FMC-6000 Flight Management Systems;
- Dual Collins GPS-4000 System;
- Dual Collins VIR-432 VHF Nav Receivers;
- Collins TRW-854 / 14" Weather Radar System;
- Dual Weather Radar Control Panels;
- Collins ALT 55B Radio Altimeter;
- Safe Flight
- Allied Signal EGPWS with Terrain/Obstacle Awareness Display and Windshear;
- Artex ELT C406-2 Emergency Locator Transmitter;
- SB604-34-031 Precision Plus Upgrade;
- Triple Collins Data Concentrator Units (DCU);
- Triple Inertial Reference Systems (IRS);
- Triple Collins VHF-422D VHF Communication System;
- Dual Collins HF-9000 HF Communications System;
- Dual Collins DME-442 Distance Measuring Equipment;
- Dual Collins ADF-462 Automatic Direction Finders;
- Dual Collins TDR-94D Mode S Transponders;
- Collins WX 1000 E LDS (Stormscope);

- Airborne Flight Information System (AFIS);
- Dual Collins RTU-4000 Radio Tuning Units;
- Collins SAT-906/6 SATCOM System – SELCAL;
- Collins TCAS II with Ch.7.1;
- Cockpit Voice Recorder – 120 min (SSCVR);
- Fairchild F1000 Flight Data Recorder (FDR);
- SB604-34-033 3D Map/Long Range Cruise Upgrade.
- Flight I.D.;
- RVSM;
- FM Immunity;
- RNP5;
- 8.33 Spacing;
- MNPS;
- RNP10.

## AIRCRAFT MODIFICATIONS

- Lightning Detection system (LDS) deactivation;
- Ice and Rain protection
- Special check/modification – GlobalPositioning System (GPS)
- Voice Recording system – new solid-state, 120 minute cockpit voice recorder system;
- Satellite communication system (satcom) - installation of the future air navigation system (FANS) and true north Iridium satellite communication system;
- Global Positioning System (GPS)
- wide area augmentation system (WAAS) capable GPS system;
- Air Traffic Control (ATC) transponder system - with automatic dependent surveillance-broadcast ADS-B Out v2 capability.



# 1998 Challenger 604 SN 5368

## Maintenance

Check History:	Last Performed Date:	Cycles:	Next Due Date:	Remaining Cycles:
Airframe 24 Months	04.Oct.2023		04.Oct.2025	
Airframe 36 Months	22.Oct.2022		22.Oct.2025	
Airframe 48 Months	30.Nov.2022		30.Nov.2026	
Airframe 96 Months	30.Nov.2022		30.Nov.2030	
Airframe 4800 Landings		4796 CSN		1309 CY
Airframe 7800 Landings		7717 CSN		7230 CY

## INTERIOR

Refurbished 2016;


- Executive nine/ten (9/10) passenger configuration with forward right hand galley;
- Forward four (4) place club;
- Aft three/four (3/4) place berthing divan opposite of a two (2) place club;
- Aft lavatory and vanity with aft baggage access.
- Galley Features: Coffeemaker; TIA Microwave Oven; Ready Hot Instant Hot Water Dispenser; TIA Hi-Temp Oven; Hot Liquid Container.

## EXTERIOR

White coat with blue and dark gray accent stripes - Last paint performed 2015 in Norwich.



# 1998 Challenger 604 SN 5368



A	FLASHLIGHT	X1
	DEFIBRILLATOR (AED)	X1
	SUPPLEMENTAL FIRST AID KIT	X1
B	FIRE CONTAINMENT KIT	X1
	EMERGENCY MEDICAL KIT	X1
	FIRST AID KIT	X1
C	HALON FIRE EXTINGUISHER CABIN	X1
D	PASSENGER LIFE VEST	X1



	CREW LIFE VEST	X1
	FIRE CONTAINMENT KIT	X1
E	HALON FIRE EXTINGUISHER CABIN	X1
	SMOKE HOOD	X3
	PORTABLE O2 BOTTLE W/ MASK	X1
F	PORTABLE O2 BOTTLE W/ MASK	X1
	FLASHLIGHT	X1
G	CREW LIFE VEST	X1

H	LIFE RAFT	X1
	PASSENGER LIFE VEST	X1
I	OXYGEN OUTLET	X1
J	NEBULIZER KIT	X1
	FLASH LIGHT	X1
K	CRASH AXE	X1
	HALON FIRE EXTINGUISHER CKPT	X1



## 1998 Challenger 604 SN 5368

---





## 1998 Challenger 604 SN 5368



## 1998 Challenger 604 SN 5368











# 1998 Challenger 604 SN 5368



Freestream Aircraft Limited is proud to have a team of highly experienced and uniquely qualified aviation consultants. Our team is able to cover all aspects of aircraft brokerage, acquisition, marketing, sales, custom design services, import/export and maintenance review of your aircraft. We specialize in state of the art, medium through ultra-long range corporate jet aircraft and fully understand the importance of attending to all details as required by our clients.

Additionally, our affiliation with brokerage firms worldwide and our collateral buying power with the aircraft manufacturers, assures professional assistance to international and multinational companies as well as private individuals, artists, royalty and head-of-state clients.

Freestream's expertise, commitment to integrity, and vast experience provide our clientele the exclusive opportunity to experience a seamless transaction in a timely manner. Principals the world over continue to find their experience with Freestream advantageous and beneficial.

### **Freestream Aircraft Limited**

29 Bruton Place London W1J 6NJ, UK  
+44 20.7584.3800

### **US Representative Office**

Teterboro Airport  
200 Fred Wehran Drive, Teterboro, NJ 07608  
+1 201.596.5051

[www.freestream.com](http://www.freestream.com)

